# RoSPA Risk Assessments

#### 6 July 2025

4. Scores of 1 to 7 inclusive are considered to be low risk and are considered to be tolerable where this is the innate risk of the item, but where remedial works are identified these should be undertaken,

5. Scores of 8 to 12 are considered to be medium risk and some control measures may be identified to reduce the risks to low, tolerable levels,

6. Score of 13 and above are considered to be high risk and urgent action is considered to be necessary to reduce the risks to tolerable levels.

Gates		Innate risk score:
Description	Tasks	Risk score
Trip points on the surface.	Make level.	9
Fencing - Stone Wall		Innate risk score:
Description	Tasks	Risk score
No Findings		
Fencing - Bow-Top		Innate risk score:
Description	Tasks	Risk score
No Findings		
Seating		Innate risk score:
Description	Tasks	Risk score
No Findings		
Litter Bins		Innate risk score:
Description	Tasks	Risk score
No Findings		
Signage - Info/Opera	tor	Innate risk score:
Description	Tasks	Risk score
No Findings		
Signage - Fitness Equ	ipment	Innate risk score:
Description	Tasks	Risk score

No Findings



Swing - Junior - 1 Bay 2 Area)	2 Seat (Outside Main Play	Innate risk score:
Description	Tasks	Risk score
Chains links worn.	Monitor for further deterioration and replace before 40% wear.	12
Surface needs repair.	Repair.	9
Adult Fitness - Cross T	rainer	Innate risk score:
Description	Tasks	Risk score
The bearings are worn.	Replace the worn bearings.	12
Cap missing.	Replace.	3
Adult Fitness - Air Wal	lk	Innate risk score: 7
Description	Tasks	Risk score
Item is worn.	Repair.	8
Adult Fitness - Surfer		Innate risk score:
Description	Tasks	Risk score
Item is worn.	Repair.	8
Paintwork is in poor condition.	De-scale back to good base material and coat with lead free paint, using appropriate precautions. Repairs may be necessary where corrosion is severe	<b>4</b>

### Swing - Toddler - 1 Bay 2 Seat

Innate	risk score	:
--------	------------	---

4

Description	Tasks	Risk score
Some chain wear.	Monitor for further deterioration and replace before 40% wear.	7
Moving parts require greasing.	Apply lubricant according to the manufacturer's instrutions.	3
Surface is wearing.	Monitor for significant deterioration and rectify when necessary.	3



Adult Fitness - Leg Press		Innate risk score: 7
Description	Tasks	Risk score
Item has some parts missing.	Replace the missing parts.	3
Item has corrosion.	Treat and repair.	3
Adult Fitness - Chest Pres	s/Lat Pull Down	Innate risk score:
Description	Tasks	Risk score
Item has some parts missing.	Replace the missing parts.	3
Adult Fitness - Rower		Innate risk score:
Description	Tasks	Risk score
Item has corrosion.	Treat and repair.	4
	No reasonably practicable action is	3

### **Carousel - Whirl - Pineapple**

Description	Tasks	Risk score
There is wear in the bearings.	Monitor and replace when necessary.	6
Clearance between the underside of the roundabout and the surface is incorrect.	No reasonably practicable action is identified.	4
Surface is wearing.	Monitor for significant deterioration and rectify when necessary.	3

## **Multiplay - Rainbow**

Description	Tasks	Risk score
Delamination of wood.	Repair.	6
Item is damaged.	Replace.	3
Item has corrosion.	Treat and repair.	3

## Swing - Junior - 1 Bay 2 Seat

Description	Tasks	Risk score
Item is cracked.	Repair.	6

#### Innate risk score:



2		
3		

#### Innate risk score:

5

Innate risk score:

PS2

5

#### Primary Items Summary – FULL DETAILS BELOW with Photographs

Item has corrosion. Moving parts require greasing.	Treat and repair. Apply lubricant according to the manufacturer's instrutions.	4
Carousel - Turnstile		Innate risk score: 5
Description	Tasks	Risk score
No Findings		
Multiplay - Nursery Rhyme		Innate risk score:

Description	Tasks	Risk score
The barrier height is below the minimum of 700 mm, when measured from the surface of the platform, stairs or ramp.		4
Rocker - Pony		Innate risk score:
Description	Tasks	Risk score
The spring is rusty. These have been known to fail without warning, leading to a collapse of the unit.	Monitor.	3
Surface is wearing.	Monitor for significant deterioration and rectify when necessary.	3
Rocker - Seesaw - Birds		Innate risk score:
Description	Tasks	Risk score
The spring is rusty. These have been known to fail without warning, leading to a	Monitor.	3

collapse of the unit.



Barriers - Swing		Innate risk score:
Description	Tasks	Risk score
Timber is decayed.	Replace affected parts.	8
Edges not radiused or chamfered.	Provide a 3 mm radius or 3 mm chamfer.	8
BBQ x 2		Innate risk score:
		4
Description	Tasks	Risk score
Algae growth giving slippery conditions.	Powerwashing is recommended. Care should be taken to ensure that the material can sustain high pressure washing.	6
Fencing - Mixed		Innate risk score: 3
Description	Tasks	Risk score
Timber is decayed.	Check on a routine basis.	4
Gate - Kissing		Innate risk score:
Description	Tasks	Risk score
No Findings		
Gate - Maintenance - Unl	ocked	Innate risk score: 4
Description	Tasks	Risk score
No Findings		
Pathways - Internal		Innate risk score:
Description	Tasks	Risk score
No Findings		
Shelter - Seating		Innate risk score: 3
Description	Tasks	Risk score
Fittings are rusty.	Replace.	4

AS1

Seating - Benches - Mixed		Innate risk score:
Description	Tasks	Risk score
No Findings		
Seating - Picnic Tables		Innate risk score:
Description	Tasks	Risk score
The equipment is dirty or algae covered.	Clean off.	2
Litter Bins		Innate risk score:
Description	Tasks	Risk score
No Findings		
Signage - Info/No Dogs/Operator		Innate risk score:
Description	Tasks	Risk score
No Findings		
Signage - Warning Overhead Wires		Innate risk score:
Description	Tasks	Risk score

**No Findings** 

